

**Photographic Documentation Log, Revision 1**  
**Puerto Rico Olefins Asbestos Site**  
**Peñuelas, Puerto Rico**  
**November 21, 2013 and December 13, 2013**



**Photo 1:** Samples ACM-001-001 and ACM-001-002 being collected from the Site on November 21, 2013.



**Photo 2:** Samples ACM-001-001 and ACM-001-002 being collected from the Site on November 21, 2013.



**Photographic Documentation Log, Revision 1**  
**Puerto Rico Olefins Asbestos Site**  
**Peñuelas, Puerto Rico**  
**November 21, 2013 and December 13, 2013**



**Photo 3:** Sample ACM-002-001 being collected from the Site on November 21, 2013.



**Photo 4:** Close up of Sample Location ACM-002-001 which was collected from the Site on November 21, 2013.



**Photographic Documentation Log, Revision 1**  
**Puerto Rico Olefins Asbestos Site**  
**Peñuelas, Puerto Rico**  
**November 21, 2013 and December 13, 2013**



**Photo 5:** Samples ACM-003-001, S0001-0006-001 and W-001-001 being collected from the Site on November 21, 2013.



**Photo 6:** Samples ACM-003-001, S0001-0006-001 and W-001-001 being collected from the Site on November 21, 2013.



**Photographic Documentation Log, Revision 1**  
**Puerto Rico Olefins Asbestos Site**  
**Peñuelas, Puerto Rico**  
**November 21, 2013 and December 13, 2013**



**Photo 7:** Samples locations S0002-0006-001 and S0002-0006-002 which were collected from the Site on November 21, 2013.



**Photo 8:** Samples S0002-0006-001 and S0002-0006-002 being collected from the Site on November 21, 2013.



**Photographic Documentation Log, Revision 1**  
**Puerto Rico Olefins Asbestos Site**  
**Peñuelas, Puerto Rico**  
**November 21, 2013 and December 13, 2013**



**Photo 9:** Samples location ACM-004-001 which were collected from the Site on November 21, 2013.



**Photo 10:** Sample W-002-001 being collected from the Site on November 21, 2013.



**Photographic Documentation Log, Revision 1**  
**Puerto Rico Olefins Asbestos Site**  
**Peñuelas, Puerto Rico**  
**November 21, 2013 and December 13, 2013**



**Photo 11:** Sample W-002-001 being collected from the Site on November 21, 2013.



**Photo 12:** Sample Location W-003-001 which was collected from the Site on November 21, 2013.

**Photographic Documentation Log, Revision 1**  
**Puerto Rico Olefins Asbestos Site**  
**Peñuelas, Puerto Rico**  
**November 21, 2013 and December 13, 2013**



**Photo 13:** Sample W-003-001 being collected from the Site on November 21, 2013.



**Photo 14:** Sample Location W-004-001 which was collected from the Site on November 21, 2013.



**Photographic Documentation Log, Revision 1**  
**Puerto Rico Olefins Asbestos Site**  
**Peñuelas, Puerto Rico**  
**November 21, 2013 and December 13, 2013**



**Photo 15:** Sample Location W-004-001 which was collected from the Site on November 21, 2013.



**Photo 16:** Sample Location W-005-001 which was collected from the Site on November 21, 2013.



**Photographic Documentation Log, Revision 1**  
**Puerto Rico Olefins Asbestos Site**  
**Peñuelas, Puerto Rico**  
**November 21, 2013 and December 13, 2013**



**Photo 17:** Sample W-005-001 being collected from the Site on November 21, 2013.



**Photo 18:** Sample Location S0003-0006-001 which was collected from the Site on November 21, 2013.



**Photographic Documentation Log, Revision 1**  
**Puerto Rico Olefins Asbestos Site**  
**Peñuelas, Puerto Rico**  
**November 21, 2013 and December 13, 2013**




**Photo 19:** Sample S0003-0006-001 being collected from the Site on November 21, 2013.



**Photo 20:** Sample W-006-001 being collected from the Site on November 21, 2013.



**Photographic Documentation Log, Revision 1**  
**Puerto Rico Olefins Asbestos Site**  
**Peñuelas, Puerto Rico**  
**November 21, 2013 and December 13, 2013**




**Photo 21:** Sample Location W-007-001 which was collected from the Site on November 21, 2013.



**Photo 22:** Sample W-008-001 being collected from the Site on November 21, 2013.



**Photographic Documentation Log, Revision 1**  
**Puerto Rico Olefins Asbestos Site**  
**Peñuelas, Puerto Rico**  
**November 21, 2013 and December 13, 2013**



**Photo 23:** Sample Location W-009-001 which was collected from the Site on November 21, 2013.



**Photo 24:** Sample P0001-ACM005-01 being collected from the Site on December 13, 2013.

**Photographic Documentation Log, Revision 1**  
**Puerto Rico Olefins Asbestos Site**  
**Peñuelas, Puerto Rico**  
**November 21, 2013 and December 13, 2013**



**Photo 25:** Sample Location P0001-ACM006-01 which was collected from the Site on December 13, 2013.